

Improvements to ViscoStar III / microViscoStar Firmware

INTRODUCTION

This document highlights the most important enhancements, changes, and bug fixes made to the Wyatt Firmware. Please contact us at support@wyatt.com if you have any questions or suggestions.

CONTENTS

Introduction.....	1
Version History.....	1
4.1.1.1	1
Improvements and Bug Fixes	1
4.1.1.0	2
Initial Release of microViscoStar	2
Improvements and Bug Fixes	2
4.1.0.26.....	2
Improvements and Bug Fixes	2
4.1.0.25.....	2
Initial Release.....	2

VERSION HISTORY

4.1.1.1

Improvements and Bug Fixes

- Added a security update to further ensure that your instrument is not susceptible to network-based malware. (#19698)

4.1.1.0

Initial Release of microViscoStar

Improvements and Bug Fixes

- Fixed tuning temperature loading issue (#18280)
- Fixed issue running firmware updaters not disabling heaters. (#18611)
- Modified firmware updater so that antivirus scanners do not report false positives when scanning our updater. (#18550)

4.1.0.26

Improvements and Bug Fixes

- Added new logging methods, which provide numeric codes along with detailed messages. (#17062)
- Fixed the "Restore Factory Offsets" button on the front panel, so that it will properly reset the factory calibration values. (#17065)
- The Transducer Protection System provides more detailed alarm and logging messages. (#17076)

4.1.0.25

Initial Release

Copyright © 2020 Wyatt Technology Corporation. All rights reserved.

Please contact Wyatt Customer Support if you need more information about changes in earlier versions of the firmware.